CONNECTING TO SIGNALVIEW, AND LOGGING DATA

NOTE: OPERATIONS MUST BE PERFORMED IN THIS ORDER

1. Select the device type from the pull-down menu
2. Select the COM port identified above
3. If you would like data to be logged click the Log Data While Running switch
   a. Switch will be up and ON will be displayed
4. Click Run Button
   a. Green Light will be on and Running will be displayed
5. Select Filename in the dialog box that appears
   a. Data is logging and will continue until stop is pressed
6. Click Stop to stop logging data

VIEWING, ANALYZING, AND EXPORTING LOGGED DATA IN SIGNALVIEW

NOTE: OPERATIONS MUST BE PERFORMED IN THIS ORDER

1. Click on Viewing Saved Data Tab
2. If you would like data to be exported to a spreadsheet file click the Export to spreadsheet after loading? switch
   a. Switch will be up and ON will be displayed
3. Click Run Button
   a. Green Light will be on and Running will be displayed
4. Click Load File Button
5. Select previously logged data file in the dialog box that appears
6. Select location of spreadsheet data export in the dialog box that appears
   a. Data will be exported to the file you select in a spreadsheet viewable format
7. Click on the magnifying glass above the plot
8. Choose the select area tool
9. Click and drag a box around the data you wish to view